
# APT TESTING AND RESEARCH PRIVATE LIMITED

APPROVED BY FDA - MAHARASHTRA STATE LIC NO. - 37-PD/TL/7 ISO 9001:2015 CERTIFIED LABORATORY (Regd. No. QMS.91.002.04.16)

Regd. Office: S. No. 36/1/1, M.N. 199, Vadgaon Khurd, Pune 411 041, Maharashtra, India. • Tel.: 020 - 6533 9233 / 6530 4803 • E-mail: ntcpune@gmail.com • Web: ntc-apt.com





STUDY CODE NO.PM357/1819/1552 ntcpune@gmail.com

www.ntc-apt.com

REGISTRATION NO. 40/PO/ReBiRc/S/99/CPCSEA

MINISTRY OF ENVIRONMENT AND FORESTS, GOVERNMENT OF INDIA

REPORT

PHOTODEGRADATION OF PLASTIC MATERIALS

OF

"GARBAGE BAG"

AS PER ASTM D 5208-91.

**TESTING FACILITY:** 

APT TESTING AND RESEARCH PVT.LTD., S.N.36/1/1, M.N.199, VADGAON KHURD, PUNE- 411 041, MAHARASHTRA, INDIA.

SPONSOR:

PINNACLE INNOVATORY SERVICES PVT. LTD.,
B-408, HILL SIDE CHS., RAHEJA VIHAR, CHANDIVALI FARM ROAD,
CHANDIVALI, ANDHERI (EAST), MUMBAI - 400072,
MAHARASHTRA, INDIA.

STUDY CODE NUMBER: "PM357/1819/1552"

REPORT NUMBER: "PM357/1819/1552"

DATE: 11/MARCH/2019 TOTAL NO. 12 PAGES IN THIS REPORT



# **CONTENTS**

STATEMENT OF COMPLIANCE	03	
QUALITY ASSURANCE STATEMENT	04	
QUALITY ASSURANCE STATEMENT STUDY INFORMATION	05	
SUMMARY	06	
INTRODUCTION	07	
REGULATORY GUIDELINES	07	
STUDY PERSONNEL	07	
MATERIALS AND METHODS	08	
STUDY DESIGN	08	
RESULTS	09	
CONCLUSION	10	1
REPORT DISTRIBUTION	11	The State of
ARCHIVES	11	00000000
CERTIFICATE	12	A STREET, STRE
		Sandalana sandana
	. R. /	
197	07/	
पे वि सा न		
1, 311, 1		



## STATEMENT OF COMPLIANCE

We, the Undersigned hereby declare that this Study Code No. "PM357/1819/1552" entitled photo degradation of plastic materials of "GARBAGE BAG" by exposure to UV light was performed study was conducted in compliance Photo degradation of plastic materials with ASTM D 5208-91. Characterization of the test material was performed by the sponsor. The objective laid down in the study protocol was achieved. No Unforeseen circumstances were observed which might have affected the quality or integrity of the study.

This test report is valid for the specified test material tested at the time of study under the stated environmental condition.

This report represents a true and accurate report of the results obtained.

We accept the responsibility for validity of the data, as well as the interpretation, analysis, documentation and reporting of the results.

This report contains 12 pages including Contents, Certificate and Tables.

Dr. K. G. Apte,

Damler P. Mrs. R.P. Damle,

Study Director.

II of fam.

Q. A

Date: 11/March/2019.



# **QUALITY ASSURANCE STATEMENT**

This study report has been reviewed by the Quality Assurance Unit of APT TESTING AND RESEARCH PVT. LTD., for compliance of plastic materials for photo degradation as per ASTM D 5208-91, Study plan, Study Data and applicable Operating Procedures.

This statement confirms that the study report accurately reflects Study data.

The summary of inspections performed during the course of the study is as follows:

S. No.	Phases of Study inspected	Date of Inspection	Type of Inspection
1	Draft Study Plan	21/February/2019	Study Based Inspection
2	Definitive Study Plan	22/February/2019	
3	Initiation of Test	22/February/2019	
4	Raw Data	07/March/2019	
5	Draft Report	07/March/2019	
6	Final Report	11/March/2019	

Name

: Mrs. R. P. Damle,

Date: 11/March/2019.

Head Q. A.:

James F



STUDY CODE NO.PM357/1819/1552

1. STUDY INFORMATION:

Study Code Number: "PM357/1819/1552"

Report Number

: "PM357/1819/1552"

**Study Title** 

: Photo degradation of plastic materials

"GARBAGE BAG"

Sponsor

: Pinnacle Innovatory Services Pvt. Ltd.,

B-408, Hill Side Chs., Raheja Vihar,

Chandivali Farm Road, Chandivali, Andheri (East),

Mumbai - 400072, Maharashtra, India.

**Testing Facility** 

: APT TESTING AND RESEARCH PVT. LTD.,

S. N. 36/1/1, M. N. 199,

Vadgaon Khurd, Pune 411 041,

Maharashtra, India.

Date of Submission of Final Report: 11/March/2019.

**Study Director** 

: Dr. K. G. Apte

Date

: 11/March/2019.

Approved for issue

Sign

Page 5 of 12



#### 2. SUMMARY:

The objective of the study now reported was to evaluate the Photo degradation of plastic materials "GARBAGE BAG" exposed to UV light. The test cycle used was as per Cycle C and exposed continuously for 200 hours under laboratory conditions.

After 200 hours exposure, the slight Photo degradation was observed. The test material showed signs of breakdown of the plastic sheets.

The test material "GARBAGE BAG" showed 07.70% photo degradation.





## 3. INTRODUCTION:

The study was conducted to evaluate the Biodegradability of the test material "GARBAGE BAG" exposure to UV light and following the Standard photo degradation of plastic materials as per ASTM D 5208-91 Test Guidelines.

# 3.1 OBJECTIVE

This study was designed to determine the degradability to the photo degradation and to establish the degradation properties of the test material.

## 3.2 TEST GUIDELINES:

ASTM BIODEGRADATION GUIDELINES, ASTM D 5208-91

of to to

## 3.3 STUDY PERSONNEL

Study Director

: Dr. K. G. Apte, M.Sc., Ph.D.

Research Associate

: Mr. S. A. Kashid, M. Sc.

Q. A.

: Mrs. R. P. Damle, M. Sc.



4. MATERIALS AND METHODS:

#### 4.1 TEST MATERIAL

#### TEST MATERIAL NOT DRAWN BY ATR

Characterization of the test material was done by the Sponsor.

Test MATERIAL

"GARBAGE BAG"

Physical State

: Bag

**Quantity Received** 

20

Batch No.

Not Mentioned

Manufacturing Date

: Not Mentioned

**Expiry Date** 

: Not Mentioned

Sponsor

: Pinnacle Innovatory Services Pvt. Ltd.

B-408, Hill Side Chs., Raheja Vihar,

Chandivali Farm Road, Chandivali, Andheri (East),

Mumbai - 400072, Maharashtra, India.

Date of Test Material Receipt

20/February/2019

Date of Initiation of Study

22/February/2019

Date of Completion of Study

05/March/2019

## 4.2 STUDY DESIGN

Biodegradable film was exposed to UV light. The test cycle used was as per

Cycle C and exposed continuously for 200 hours under laboratory

A to

conditions.

ज्ञा न



## 5. RESULTS:

After 200 hours exposure, the "GARBAGE BAG" showed 07.70% Photo degradation. The test material showed signs of breakdown of the plastic sheets.

	Results			
Properties	Before UV Exposure	After UV Exposure of 200 Hrs	% reduction	
Tensile Strength (Kg)	2.600	2.400	7.70	
1-1				





## 6. CONCLUSION:

It can be concluded that the test material "GARBAGE BAG" Showed signs of Photo degradation through UV exposure.

This test report is valid for the specified test material tested at the time of study under the stated environmental condition.






#### 7. REPORT DISTRIBUTION:

Two original copies of study reports are prepared and submitted to Sponsor.

# 8. ARCHIVES:

All raw data and other documents, a photocopy of the final test report, will be stored in the archive of APT TESTING AND RESEARCH PVT. LTD., for a period of five years from the date of submission of the final report.



# APT TESTING AND RESEARCH PRIVATE LIMITED

APPROVED BY FDA - MAHARASHTRA STATE LIC NO. - 37-PD/TL/7 ISO 9001:2015 CERTIFIED LABORATORY (Regd. No. QMS.91.002.04.16)





# CIN-U74220PN2008PTC132043

STUDY CODE NO.PM357/1819/1552

Date: 11/March/2019.

# CERTIFICATE

This is to certify that the test material "GARBAGE BAG, supplied by Pinnacle Innovatory Services Pvt. Ltd., B-408, Hill Side Chs., Raheja Vihar, Chandivali Farm Road, Chandivali, Andheri (East), Mumbai - 400072, Maharashtra, India, according to the Photo degradation of plastic materials as per ASTM D 5208-91, was found to show signs of PHOTODEGRADATION by the tests studied by exposed to UV light.

The report of the test conducted has been submitted through Study Code No. "PM357/1819/1552."

This test report is valid for the specified test material tested at the time of study under the stated environmental condition.

The test material "GARBAGE BAG", showed 07.70% of photo degradation.

ATR is approved by the Food & Drug Administration, Maharashtra State, Pune, through License No. 37-PD/TL/7.

(Dr. K. G. Apte),

Study Director.

Page 12 of 12